

SERVICE PACK MOLDING PRESSES

1.Inclined surfaces.

Milling of flat surfaces arranged in direction other than bubble level.

2. Deep damages.

Milling of surface to remove damages by milling of minimum allowance.

3. Deformation.

Milling of surface to restore flatness required.

4. Cylindrical surfaces.


Repair by boring machine of nut screw seat (e.g on friction screw press) and similar surfaces.

Working Range.

No limit.

Customization.

Available for anchoring and support of activities by Laser Tracker tolerance check.



NUIE		

24/7 | Worldwide Site Machining

We perform on-site machining and take care of all those interventions aimed at the restoring of the geometry of mechanical components. In addition to being first-users of a wide range of machine tools, we are resellers and consultants too. Our experience is mostly related to the Oil & Gas Industry, but we easily manage to apply our services in any kind of industry.

